

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L10	2174478	(range or distance) finder and (hand near held or portable)	USPAT	OR	OFF	2005/11/02 15:41
L11	2087928	(range or distance) finder and (hand near held or portable)	USPAT	OR	OFF	2005/11/02 15:41
L12	2087594	(range or distance) finder and (hand near held or portable) and laser	USPAT	OR	OFF	2005/11/02 15:42
L13	570	(range or distance) finder and (hand near held or portable) and laser	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	NEAR	OFF	2005/11/02 15:42
L15	871741	DE "4121625"	USPAT	OR	OFF	2005/11/02 16:00
L16	0	DE4121625	USPAT	OR	OFF	2005/11/02 16:00
L17	871741	DE "4121625"	USPAT	OR	OFF	2005/11/02 16:00
L18	62311	L15 and laser	USPAT	OR	OFF	2005/11/02 16:00
L19	51368	L18 and (range or distance)	USPAT	OR	OFF	2005/11/02 16:01
L20	65227	L18 and (range or distance) finder	USPAT	OR	OFF	2005/11/02 16:01
L21	0	DE "4121625"	USPAT	NEAR	OFF	2005/11/02 16:02
L22	3	"4121625"	USPAT	NEAR	OFF	2005/11/02 16:09
L23	0	((("EP269276") or ("DE20022511") or ("DE10055510") or ("DE4121625")).PN.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/11/02 16:10
L24	2	("20050120963").PN.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/11/02 16:16
L25	782	(356/4.01,3.01).CCLS.	US-PGPUB; USPAT; USOCR	OR	OFF	2005/11/02 16:27
L26	2	L25 and (LED or light) near7 (notify or notification or warn)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	NEAR	ON	2005/11/02 16:28

L27	563	(LED or light) near7 (notify or identify) near7 (switch or button or input)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	NEAR	ON	2005/11/02 16:29
L28	3	L27 and range finder	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	NEAR	ON	2005/11/02 16:30
L29	3	L27 and (distance or range) finder	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	NEAR	ON	2005/11/02 16:30
L30	72	L27 and laser	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	NEAR	ON	2005/11/02 16:30
L32	75	illuminated near mark\$3 and button	USPAT	OR	OFF	2005/11/02 16:35
L34	1172	laser (distance or range) and (hand held or portable)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	NEAR	ON	2005/11/02 16:39
L35	1	L34 and illuminated marking	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	NEAR	ON	2005/11/02 16:41
L36	6	button same illuminated marking	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	NEAR	ON	2005/11/02 16:41
L38	8002	computer near keyboard	USPAT	OR	OFF	2005/11/02 16:45
L39	3343	L38 and keys	USPAT	OR	OFF	2005/11/02 16:45
L40	62	L39 and illuminated same keys	USPAT	OR	OFF	2005/11/02 16:45
L41	33	L40 and LED	USPAT	OR	OFF	2005/11/02 16:45
S1	753	(356/4.01,3.01).CCLS.	US-PGPUB; USPAT; USOCR	OR	OFF	2005/11/02 16:26

S2	30	S1 and hand near held	USPAT	OR	OFF	2005/07/29 09:32
S3	51	S1 and (hand near held or portable)	USPAT	OR	OFF	2005/11/02 15:40
S4	7	(hand near held or portable) near rangefinder	USPAT	OR	OFF	2005/11/02 16:00
S5	2	((("5926260") or ("5148411")).PN.	USPAT; USOCR	OR	OFF	2005/07/28 13:45
S6	1	S1 and multiple near (inputs or triggers)	USPAT	OR	OFF	2005/07/28 13:49
S14	355	laser near rangefinder	USPAT	OR	OFF	2005/07/28 14:11
S15	1	S1 and illuminated near mark\$3	USPAT	OR	OFF	2005/11/02 16:35
S16	0	S1 and illuminated near button	USPAT	OR	OFF	2005/07/28 14:17
S17	106	S1 and illuminated	USPAT	OR	OFF	2005/07/28 14:18
S19	205	illuminated near button	USPAT	OR	OFF	2005/07/28 14:18
S20	13	S19 and hand near held	USPAT	OR	OFF	2005/07/28 14:19
S21	144156	((("356") or ("33")).CLAS.	USPAT; USOCR	OR	OFF	2005/10/31 15:22
S22	313	S21 and measure same (distance same (velocity or reflectivity))	USPAT	OR	OFF	2005/07/28 16:08
S23	12	S22 and button	USPAT	OR	ON	2005/07/28 16:02
S27	20	distance.near velocity near measure	USPAT	OR	OFF	2005/07/28 16:14
S28	20	distance near (velocity or reflectivity) near measure	USPAT	OR	OFF	2005/07/28 16:14
S29	7869	computer near keyboard	USPAT	OR	OFF	2005/07/29 08:00
S30	3287	S29 and keys	USPAT	OR	OFF	2005/07/29 08:00
S32	125	S30 and shift near keys	USPAT	OR	OFF	2005/07/29 08:09
S33	0	S32 and illumintaed near keys	USPAT	OR	OFF	2005/07/29 08:26
S34	0	S32 and illumintae	USPAT	OR	OFF	2005/07/29 08:26
S35	0	S32 and illumintaed	USPAT	OR	OFF	2005/07/29 08:26
S36	8	S30 and illuminated near keys	USPAT	OR	OFF	2005/07/29 08:35
S38	61	S30 and illuminated same keys	USPAT	OR	OFF	2005/11/02 16:45
S39	50	Laser near rangefinder and keyboard	USPAT	OR	OFF	2005/07/29 09:33
S40	9	S "21" and inputs same "or" connected	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	NEAR	ON	2005/10/31 15:27
S41	4	((("5926260") or ("5148411")).PN.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/10/31 15:27

S42	13046	measure and laser and (hand held or portable)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	NEAR	ON	2005/11/01 12:48
S43	3	measure near5 multiple near5 buttons	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	NEAR	ON	2005/11/01 12:35
S44	10	S42 and measure buttons	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	NEAR	ON	2005/11/01 12:42
S45	4	((("5926260") or ("5148411")).PN.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/11/01 12:45
S46	1	S42 and different near4 measur\$4 near3 buttons	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	NEAR	ON	2005/11/01 12:46
S47	10	S42 and measure button	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	NEAR	ON	2005/11/01 12:47
S48	2	S42 and measure trigger	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	NEAR	ON	2005/11/01 12:47
S49	1172	laser (distance or range) and (hand held or portable)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	NEAR	ON	2005/11/02 16:39